Garrett County Department of Public Works

Roads Division
Public Service Center
2008 Maryland Highway, Suite 3
Mt. Lake Park, MD 21550
Phone (301) 334-7488
Fax (301) 334-7489



Utilities Division
Public Service Center
2008 Maryland Highway, Suite 2
Mt. Lake Park, MD 21550
Phone (301) 334-6983
Fax (301) 334-6984

TELEPHONE REPORT OF SEWAGE OVERFLOW

Date and Time of Report:	December 3, 2018 12:23 pm
The date and time when the overflow began and stopped or, if not stopped, the date and time the overflow is expected to be stopped;	December 3, 2018 12:23 pm Began 12/3/18 @ 728m; Stopped 12/3/18 @828m
Whether the overflow is from a combined sewer system (CSO), a separate sanitary sewer system (SSO), or a treatment plant bypass;	SSO
The location of the overflow, including latitude and longitude if reasonably available, Maryland Grid Coordinates or nearest street and intersection, city or town, zip code; The name of the owner, operator and telephone number of	Pump Station 8-3 50ft. North of 2053 Marsh Hill Rd MeHenry MD 21541
the sanitary sewer system or treatment plant. (Be sure to include the treatment plant associated with this	Garrett County Dept. of Public Works. Linn H. Herlsuperintendent (30) 501-1109: 387-9175
collection system)	Deep Creek Lake W.WT.P. Collections
The cause or suspected cause of the overflow;	Broken discharge line in Pumpstation basin
The name of the receiving water, if applicable including storm drains, side ditches, etc.	Deep Cræk Lake
The volume discharged based on actual measurement or as an estimate using best professional judgment;	estimated 1,650 gallon
Is the receiving water designated as shellfish waters or for a public drinking water supply:	no yes NO Drinking Water Shellfish
A description of the combined sewer system, separate sanitary sewer system or treatment plant component from which the overflow was released, such as manhole, crack in pipe, pumping station wet well or constructed overflow pipe;	1/4" crack in discharge line inside of pump station basin allowed schage to recirculate inside basin & over flow
A detailed description of visual observations and preliminary assessment of the overflow's actual or potential impact upon waters of the State;	overflowed out of pump station lid over retaining wall into drainage ditch then to lake
The steps taken or planned to reduce, eliminate, and prevent recurrence of the overflow and a time schedule for completion of the steps;	discharge line in pump station has been replaced and replumbed
Measures taken or planned to mitigate the adverse impact of the overflow and a time schedule for implementation of the measures;	Spill area will be lime Stabilized and water quality samples have been taken
Whether the public and the local Health Department have been notified, who performed the notification, the media used, and the content of the message.	health Department notified steve Sherard was on site, will notify public later tiday
Name, title and telephone number of the person reporting the overflow:	John Miller Superintendent cell (301) 501-1109 off. (301) 387-9175

Called MDE @ 123 pm Spoke to: Kathy Mohan